

HABS
WASH,
37-Sum.
1-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

United States Border Inspection Station
103 Cherry Street
Sumas
Whatcom County
Washington

HABS No. WA-182

Chuck Schwartz, Photographer March 1988

Photographs WA-181-1 through WA-182-10 are photocopies of construction drawings. Original tracings are located at the National Archives and Records Service in Seattle, Washington.

WA-182-1 APPROACH PLAN (SITE PLAN)
WA-182-2 FIRST FLOOR PLAN
WA-182-3 BASEMENT PLAN, SECOND FLOOR PLAN
WA-182-4 FRONT, REAR, AND END ELEVATIONS, BUILDING SECTION
WA-182-5 CANOPY AND GARAGE/INSPECTION SHED
WA-182-6 FOUNDATION PLAN
WA-182-7 FIRST AND SECOND FLOOR FRAMING PLANS
WA-182-8 ROOF FRAMING PLAN
WA-182-9 CHANGES IN CONCRETE DRIVEWAYS
WA-182-10 CUSTOMS AND IMMIGRATION SIGN

Photographs WA-182-11 through WA-182-21 are photocopies of historic photographs. Original views are owned by the General Services Administration, Public Buildings Service, and are located in the Sumas Border Station. The photographer is unknown.

WA-182-11 CONSTRUCTION PHOTOGRAPH, FEBRUARY 1, 1932
WA-182-12 CONSTRUCTION PHOTOGRAPH, UNDATED
WA-182-13 CONSTRUCTION PHOTOGRAPH, MARCH 5, 1932
WA-182-14 CONSTRUCTION PHOTOGRAPH, APRIL 1, 1932
WA-182-15 CONSTRUCTION PHOTOGRAPH, MAY 1, 1932

UNITED STATES BORDER INSPECTION STATION
HABS No. WA-182 (page 2)
Index to Photographs

WA-182-16 CONSTRUCTION PHOTOGRAPH, JUNE 1, 1932
WA-182-17 CONSTRUCTION PHOTOGRAPH, FROM SOUTHEAST, SEPTEMBER 1, 1932
WA-182-18 CONSTRUCTION PHOTOGRAPH, FROM EAST, SEPTEMBER 1, 1932
WA-182-19 CONSTRUCTION PHOTOGRAPH, FROM SOUTHEAST, OCTOBER 1, 1932
WA-182-20 CONSTRUCTION PHOTOGRAPH, FROM EAST, OCTOBER 1, 1932
WA-182-21 AERIAL VIEW, 1985

PRESENT-DAY VIEWS

WA-182-22 FRONT AND SIDE VIEW FROM EAST
WA-182-23 FRONT AND SIDE VIEW FROM NORTH
WA-182-24 SIDE VIEW FROM NORTHWEST
WA-182-25 SIDE VIEW FROM SOUTHWEST
WA-182-26 DETAIL VIEW FROM SOUTHWEST
WA-182-27 SIDE VIEW FROM SOUTHEAST
WA-182-28 ENTRY DOORS
WA-182-29 SECOND FLOOR WINDOW ON NORTHWEST ELEVATION
WA-182-30 FIRST FLOOR WINDOWS ON SOUTHEAST ELEVATION
WA-182-31 DETAIL VIEW OF SECOND FLOOR DORMERS
WA-182-32 DETAIL VIEW OF CORNERSTONE
WA-182-33 INTERIOR VIEW OF CUSTOMS GENERAL OFFICE
WA-182-34 INTERIOR VIEW OF IMMIGRATION GENERAL OFFICE
WA-182-35 STAIR HALL AT FIRST FLOOR
WA-182-36 SECOND FLOOR CORRIDOR
WA-182-37 WINDOW AT SECOND FLOOR DORMER
WA-182-38 CELL WINDOW AT SECOND FLOOR DORMER

UNITED STATES BORDER INSPECTION STATION
HABS No. WA-182 (page 3)
Index to Photographs

WA-182-39 ROOF TRUSSES AT ATTIC

WA-182-40 BASEMENT CORRIDOR SHOWING VAULT DOORS

WA-182-41 BOILER IN BASEMENT